



16/June/2020

PWM-KN Application/Firmware change tracking

| Date | Application Version | Firmware Version | Note |
|-------------|---------------------|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 25-Feb-2020 | Rev: 01.1 | Rev: [2]1.1 | First release |
| 15-May-2020 | Rev: 02.0 | Rev: [3]2.0 | <p>Application:</p> <ul style="list-style-type: none">1) Add DALI curve in dimming curve selection2) Add Lamp Failure state 2 <p>Firmware:</p> <ul style="list-style-type: none">1) Improve min. dimming output to 0.01%2) Ignore the dimming command when lower than min. level range <p>Remark:</p> <ul style="list-style-type: none">1. Rev:02.0 application database work with firmware version Rev[3]2.0 (shown in ETS).2. Please note this database may not work with previous firmware. <p>Click here for how to solve it.</p> |