Change Log Firmware Version 1.0.2 (10.2019)

- New: WSS (secure web sockets) support.
- New: Note on linked indoor stations when deleting outdoor stations.
- Improvement: "Instant configuration" of the EIBPORT CONTROL L visualization project via token.
- Fixed: Restore function for backup files.

NOTE:

THIS FIRMWARE VERSION REQUIRES AT LAST EIBPORT FIRMWARE VERSION 3.8.0!

Change Log Firmware Version 1.0.1 (06.2019)

- New: "ABB/ Busch-Jaeger Welcome" door intercom system implemented.
- New: "Doorbird" door intercom system implemented.
- New: "2N" door intercom system implemented.

NOTE:

THIS FIRMWARE VERSION REQUIRES AT LAST THE CONTROL T2 VERSION 1.1.17!

Change Log Firmware Version 1.0.0

Initial Version