

BUILDING AUTOMATION, 2020-11-13

Release Note

Combi Switch Actuator

SAH/S x.y.7.1 Switch/Shutter Actuator, x-fold, yA, MDRC

Product name	Switch/Shutter Actuator, x-fold, yA, MDRC (x = 8, 16, 24; y = 6, 10, 16)
Product type	SAH/S x.y.7.1
Order code	2CDG 110 xxx R0011
Current version	ETS Application: Switch/Shutter x-fold yA/1.0 Firmware: SAH_Sxy7x1_FW_XX_V0-1-6_112
Languages	EN, DE, ES, FR, IT, NL, PL, RU

Product type	Order code	Website	ETS Application	Firmware
SAH/S8.6.7.1	2CDG110244R0011	Link	Here Download V1.0 ETS Application (.knxprod) [XX] SAH/S x.y.7.1	V0.1.6
SAH/S16.6.7.1	2CDG110245R0011	Link		V0.1.6
SAH/S24.6.7.1	2CDG110246R0011	Link		V0.1.6
SAH/S8.10.7.1	2CDG110247R0011	Link		V0.1.6
SAH/S16.10.7.1	2CDG110248R0011	Link		V0.1.6
SAH/S24.10.7.1	2CDG110249R0011	Link		V0.1.6
SAH/S8.16.7.1	2CDG110250R0011	Link		V0.1.6
SAH/S16.16.7.1	2CDG110251R0011	Link		V0.1.6
SAH/S24.16.7.1	2CDG110252R0011	Link		V0.1.6

NOTE:

Always install latest software version provided. Any defects or damages due to an earlier version cannot be claimed.

ETS APPLICATION

Product Type	Version	Since	Updates and Release Notes
SAH/S x.y.7.1	1.0	10/2019	Market Introduction

FIRMWARE

Product Type	Version	Since	Updates and Release Notes
SAH/S x.y.7.1	0.1.6	11/2020	Optimization for special KNX topologies (NACK)
SAH/S x.y.7.1	0.1.5	09/2020	Correction sending failure/lost telegrams at high bus load
SAH/S x.y.7.1	0.1.3	03/2020	Optimization of programming behavior in case of doubly used KNX addresses
SAH/S x.y.7.1	0.1.2	12/2019	- Improvement of operational performance and long term stability - Behavior after bus voltage recovery
SAH/S x.y.7.1	0.1.0	10/2019	Market Introduction

For Firmware Update please use the ETS App „KNX Bus Update“ ([Engineering Guide](#))