

ChangeLog Version 1.2.3

- **Fixed:** Potential reboots when multiple apps are installed due to overly restrictive system monitoring in version 1.2.2

ChangeLog Version 1.2.2

- **Fixed:** Error in DHCP IP address assignment

ChangeLog Version 1.2.1

- **Implemented:** Retrieving physical addresses over KNXnet/IP Tunneling (hardware variant Extension)
- **Fixed:** Errors in connection handling with ETS 5 if NAT mode is enabled
- **Fixed:** DNS issues after manually changing the DNS server
- **Fixed:** Inactive instances can only be copied accompanied by an error message
- **Fixed:** Potential reboots when multiple apps are installed due to overly restrictive system monitoring in version 1.2.0

ChangeLog Version 1.2.0

- **NEW:** Support for the EnOcean hardware variant, port of the EnOcean Editor from EIBPORT
- **Fixed:** Bug in backup mechanism for apps and instances